



WIRELESS READING SCALES CONNECTION



DATA MET FUNCTIONS

<p>ANALOG SCALE</p>	<p>COLOR GO / NOGO</p>	<p>COLOR MAX / MIN / RANGE</p>	<p>TIMER</p>	<p>TOUCH PROBE SETTINGS</p>	<p>FORMULA Ax^2+Bx+C</p>
<p>GRAPHIC MODE 1D/2D</p>	<p>MEMORY 2000 values</p>	<p>FOLDERS mode</p>	<p>MEMORY STATISTICS</p>	<p>TEMPERATURE COMPENSATION</p>	<p>PASSWORD</p>
<p>DISPLAY & ENERGY</p>	<p>RESOLUTION, mm/inch</p>	<p>WIRELESS to MDS app</p>	<p>WIRELESS & USB HID</p>	<p>HUB mode (2D, Probe)</p>	<p>DEVICE INFO, UPDATE</p>

- Industry 4.0 adopted Manual **DataMet** FORCE tester with computerized MICS system with 2,4" color Touchscreen
- **DataMet FORCE tester included**
- Optional READING SCALE
- Functions: On-line Graphic, Analog scale, Go/NoGo, Max/Min, Formula, Timer, Linear correction
- Measuring HUB: Wireless MICROTECH instrument connection, Synchronization, 2D mode, 2D Graph
- Memory manager: 2000 values, Folders system, Statistics mode, Memory data transfer
- **4 MODES DATA TRANSFER:** WIRELESS to MDS app (Windows, Android, iOS, MacOS); WIRELESS HID, WIRELESS HID+MAC, USB HID
- Calibration certificate included (ISO17025 (Ilac MRA))

Item No	Load		Reso- lution	Range	Scale resolution	Weight	Preset	Go/NoGo	Max/Min	Formula	Timer	Temp comp	Linear corr	Calibr date	FW update	Recharge	Memory	WIRELESS	USB			
	N	lbF																		N	mm	mm
278170056	500	112	0,001	180	-	25	•	•	•	•	•	•	•	•	•	•	•	•	•	•		
278170057					0,005		•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
278170106	1000	225			-		•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
278170107					0,005		•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•



DELIVERY SET

FREE VERSIONS OF MDS APP

USB DATA/CHARGING CABLE

CALIBRATION PROTOCOL

OPTIONAL

DataMet BUTTON

DataMet FOOTSWITCH

MDS DISPLAY UNIT

MDS SOFTWARE

STANDARD MDS app